

Oil Field Environmental Incident Summary

Incident: 20150618150407 **Date/Time of Notice:** 06/18/2015 15:04

Responsible Party: Petro Harvester Operating Company, LLC

Well Operator: PETRO HARVESTER OPERATING COMPANY, LLC

Well Name: Evenson CTB

Field Name: WAYNE

Well File #:

Date Incident: 6/18/2015 **Time Incident:** 07:00 **Facility ID Number:** 209091-01

County: BOTTINEAU **Twp:** 162 **Rng:** 81 **Sec:** 31 **Qtr:** NE NW

Location Description: CTB located at approximately 2,030' FWL and 300' FNL - Section 31 T162 R 81

Submitted By: Gary Watson

Received By:

Contact Person: Mark Bonnie
5160 TENNYSON PARKWAY
SUITE 3000 E
PLANO, TX 75024

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 9500 Feet

Distance Nearest Water Well: 9500 Feet

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil					0	barrels
Brine	30	Barrels	30	Barrels	30	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 4/4/2016

Clean Up Concluded: 6/26/2015

Risk Evaluation:

No immediate explosive or health hazard risk.

Areal Extent:

Contained within the diked area.

Potential Environmental Impacts:

No impact to surface water or groundwater. Minimal impact to facility soil. All released fluids were contained within the diked area.

Action Taken or Planned:

Bob Garvey - NDIC - was notified telephonically. A vandalism report was filed with the Bottineau County Sheriffs Department. Released fluids contained within the dike area will be vacuumed up and pumped to the CTB produced water tanks. The affected soil will be allowed to dry, scraped-up, collected and hauled to an approved disposal facility.

Wastes Disposal Location: Approved disposal facility.

Agencies Involved: Local Law Enforcement

Updates

Date: 6/18/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to tank overflow, remained on location within the diking, according to the report. NDIC retains oversight.